

WV-U61301-Z1- Firmware Release Note

Version history	Priority Rank Level				Issue (Phenomenon)	Occurrence condition	Correspondence
	A	B	C	U			
1.00 Sept., '22	-				First production		
1.01 Sept., '22	B			x	The [Detection sensitivity] setting of VMD area is not reflected in the actual performance. (Occurrence frequency: High)	When satisfying both of the following conditions: - Preset position is configured - VMD area is configured for the preset position	Fixed.
			x		The camera may not zoom in smoothly on the image.	[Stabilizer] is enabled on the [Basic] tab	Fixed.
1.02 Sept., '22	U			x	-	-	Updated for the production management. Note: Only the version number has changed.
2.20 Sept., '22	C			x	-	-	Changed the company name in the GlobalSign digital certificate installed on the camera to "i-PRO Co., Ltd."
				x	-	-	Supports the FTP function.
				x	-	-	Supports the extension software for 3rd party application.
				x	-	-	Added the HTML initialization function. [Load the default HTML files (setup menu).] and [Reset to the default and load the default HTML files.] have been added to the [Default reset] tab.
				x	-	-	Fixed.
				x	-	-	Fixed.