



This document describes WV-X5550LT/WV-X5550LTPJ firmware upgrade info.
 1. Release version: Version 2.04
 2. Release Note Reference Number: X5550LT-005

March 1, '23
 i-PRO Co., Ltd.

WV-X5550LT and WV-X5550LTPJ Firmware Release Note

VER (ActiveX VER) Release Date	Priority Rank Level				Contents		
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence
Ver1.00 (4.50.38) August,'20	-				First production		
Ver1.01 (4.50.38) Nov.,'20	U			x	-	-	Added the following parameters to the CGI command response, for the improvement in connectivity with the Video Management System(VMS) of Genetec and Milestone. - "video_server.image.sensor.number=1" for Single source - "video_server.image.sensor.number=2" for Dual sources
Ver2.00 (4.60.30) Apr., '22	U			x	-	-	Changed company name from "Panasonic i-PRO Sensing Solutions Co., Ltd." to "i-PRO Co., Ltd."
				x	-	-	Updated SNMP extended MIB: Changed the extended Object ID(OID) from Panasonic(258) to i-PRO(57501). Note: - This change applies only to the products manufactured in April, 2022* or later, and is not applied by firmware upgrade. *Serial number: VDxxxxxx - MIB file and manual are available at the following link: https://i-pro.com/global/en/surveillance/database/i-pro-device-integration/snmp-mib
				x	-	-	Changed the alarm name from "Panasonic alarm protocol notification" to "TCP alarm notification".
Ver2.01 (4.60.30) Oct., '22	C			x	-	-	Supports the extension software for 3rd party application.
				x	The occupancy detection area information is not included in the HTTP alarm notification from the camera.	-	Fixed.
Ver2.04 (4.60.30) Mar., '23	U			x	-	-	Changed company name in the plug-in (ActiveX) software to "i-PRO Co.,Ltd."