

ITEM NO.	PART NUMBER	QTY.
1	320A211P01 or P02, Panasonic PWM40, Wall Mount Base	
2	320A213P01 or P02, Panasonic PWM40, Wall Mount Gasket	
3	400A210P02 Screw, SCH Captive, 8-32 x .875	4
4	320A053P01, Plug, .750 NPT, Liquid Tight, heyco-3547b	1
5	320A054P01, Nut, .750 NPT, Liquid Tight, heyco-8465-8466	1
6	202A168 P01 Dome Assy to housing 7 in x .046 dia. cable, 2 eyelets	1
7	400A201P95, Screw, Pan Hd. 8-32 x .25, Phillips, SS	2
8	320A212P01 or P02, Panasonic PWM40, Wall Mount Cover	1
9	320A032 Panasonic, Wall Mt. Gasket	1

NOTES: UNLESS OTHERWISE SPECIFIED

- 1. ASSEMBLE PARTS AS SHOWN.
- 2. USE ALL P01 PARTS TO ASSEMBLE MODEL 320A214P01.
- 3. USE ALL P02 PARTS TO ASSEMBLE MODEL 320A214P02.

REVISION HISTORY





FAS

ΒY

А REV

DOCUMENT UNCONTROLLED UNLESS STAMPED IN RED

	ALL DIMENSIONS IN INCHES UNLESS OTHERWISE SPECIFIED	
	TOLERANCES: FRACTIONS = ± 1/32"	
	DECIMALS $X = \pm$.030	
	$.XX = \pm .015$ $.XXX = \pm .005$ WALL MOUNT, PENDANT	
	$ANGLES = \pm 0.5^{\circ} MOUNT$	l
12/12/2019 ENC# 19044 CREATED THIS ASSEMBLY DRAWING.	DEBURR HOLES AND BREAK SHARP EDGES .005-0.15. THIS DRAWING AND THE INFORMATION IT CONTAINS HAVE BEEN FUNNISHED FOR USE BY YOUR ORGANIZATION ONLY AND FOR PURPOSES CONSISTENT WITH THE TRANS.	l
DATE ECN# AND DESCRIPTION		l
	DO NOT SCALE FROM DRAWING 1 of 1 320A214	l