

May., 2023
ay1008-83

The following models are not supported. For these models, please use P5SCT (Panasonic System Configuration Tool) V7.x.

Camera : WV-NF28*, WV-NF302, WV-NP24*, WV-NP304, WV-NP100*, WV-NS2024, WV-NS9**, WV-JT304, WV-JT314, WV-NW484, BB-HCE*, BB-HCE*, B*
Recorder : WJ-HD350, WJ-HD309, WJ-HD316A, WJ-HD150, WJ-HD180

*1: "Camera title position" setting is not supported.

*2: "Language", "Start Date/Time", "End Date/Time" settings are not supported.

*3: "Upside-down" setting is not supported.

*4: "Image rotation" setting is not supported.

*5: "Max Bit rate", "Smart Coding Mode" setting is not supported.

*6: "Adaptive black stretch", "AGC", "DNR" settings are not supported.

*7: For the audio settings, "Unicast Port2(Audio)" setting is not supported.

*8: PC must be able to connect to the Internet.

*9: "QoS" setting is not supported.

*10: You can launch the "Camera Advanced Settings" function by thumbnail menu. This function supports the following models (Firmware version 1.11 or later required).

--WV-S1136, WV-S15356, WV-S15367N, WV-S2136, WV-S22360, WV-S2236L, WV-S25366T and WV-S2136
If the firmware version of the camera is 1.4 or higher, please use version 2.3 or higher of the software.
"Audio input encoding format" and "Audio volume control mode" are not supported.

--WV-S15500, WV-S15700, WV-S25500, WV-S22700, WV-S25500 and WV-S25700, WV-S15600, WV-S22600, WV-S25500
Firmware version 1.01 or higher required.
"Audio input encoding format" and "Audio volume control mode" are not supported.

*11: You can launch the "Camera Advanced Settings" function by thumbnail menu. This function supports the following models (Firmware version 1.50 or later required. Some video and audio settings require camera firmware version 1.60 or higher).

If the firmware version of the camera is 1.6 or higher, please use version 2.3 or higher of the software.
"Audio input encoding format" and "Audio volume control mode" are not supported.

--WV-X1551LN, WV-X1571LN, WV-X2251L, WV-X2271L, WV-X2551LN, WV-X2571LN
"Audio input encoding format" and "Audio volume control mode" are not supported.

*12: Corresponds to the Extension system settings of the following models. (Starts from the thumbnail menu on the main screen.)

--WV-S4176, WV-S4576(M), WV-S4156, WV-S4556(M), WV-S71300-F3

*13: After "Application update" completion, please re-confirm the setting value / schedule settings and check the operation of application.

*14: Please refer the following.

<https://t-gps.com/global/en/surveillance/training-support/support/technical-information> [01013]

*15: You can launch the "Camera Advanced Settings" function by thumbnail menu. This function supports the following models.

--WV-S6534M, WV-S6534N, WV-S6534-ZX, WV-S6534-Z2X, WV-S6530-Z2, WV-S61300-Z1, WV-S61300-Z2, WV-S61300-Z1, WV-S65300-ZY, WV-S65301-Z1, WV-S65302-Z2, WV-S65501-Z1, WV-S61501-Z1

*16: You can launch the "Camera Advanced Settings" function by thumbnail menu. This function supports the following models.

--WV-S8543(L), WV-S8544(L), WV-S8563L, WV-S8564L, WV-S8573, WV-S8574L, WV-S86531-Z2 and WV-S86530-Z2, WV-S85702-F3L, WV-S85402-V2L

*17: You can launch the "Camera Advanced Settings" function by thumbnail menu. This function supports the following models.

--WV-S71300-F3

*18: You can launch the "Camera Advanced Settings" function by thumbnail menu. This function supports the following models.

--WV-U1130A, WV-U1132A, WV-U1142A, WV-U11324A, WV-U11424L, WV-U1210LA, WV-U12130A, WV-U12132A, WV-U12140LA, WV-U12530LA, WV-U25324L, WV-U2540LA, WV-U2542LA, WV-U85402-V2L, WV-U11300-V2, WV-U21300-V2L

*19: "App. Update" is not supported.

*20: You can launch the "Camera Advanced Settings" function by thumbnail menu. This function supports the following models.

--WV-S4156, WV-S4176, WV-S4556(M), WV-S4576(M)