

## WJ-HD616/HD716 Firmware version history

\*OS : Operating System

| Firmware | OS | Date of Issue | Contents   | Month of production |
|----------|----|---------------|--|---------------------|
| V1.04    |    | Nov.'09       | 1. Playback video stops with 1 time of frequency when it continuously playback video for more than 228 hours.<br><br>2. Appears vertical line noise at right side of live video output(Monitor Output 2) with 2 times of frequency when it uses it for more than 32,400 hours.   |                     |
| V1.06    |    | Jan,'10       | 1. Fixed firmware problem of V1.03<br>System compose : WJ-HD616(HD716), WJ-SX650 and WV-CU650<br>Phenomena : Doesn't controlled "STOP" function from CU650 when setting play back multi screen (7, 8 or 9 split) mode of HD616(HD716).   |                     |
|          |    |               | 2. Fixed firmware problem of V1.04<br>System compose : WJ-HD616(HD716), WJ-SX650 and WV-CU650<br>Phenomena : Doesn't change "MONITOR OUTPUT" operation subsequent to the 2nd time controlled from CU650  |                     |
| V1.07    |    | Jan,'10       | 1. If "HDD auto delete" is set as 1 month & actual 1 month before day is not exist, all recorded data is deleted.<br>* example : On Mar.29.'10, Feb.29.'10 is not exist. Then all recorded data was deleted.   |                     |
| V2.02    |    | Mar,'10       | 1. "GUI based operation performance" improved.<br>Refer to "Ver200_improvement.pdf" for more detail  |                     |
| V2.03    |    | May,'10       | 1. "Pre-rec images on PRE-REC mode might not be recorded" fixed.<br>2. "SD card access error" fixed  |                     |
| V2.05    |    | Oct.'10       | 1. "On manual REC or Schedule REC, even REC LED is on, recording might not work" fixed. *Very Rare case<br>2. "If trying to copy over 25,000files to DVD,copy error may happen" fixed.<br>3. "NTPd function will stop when IP address is changed" fixed.<br>4. "Block noise or colored image may be recorded at Power On time" fixed | Nov.'10             |
| V2.06    |    | Jan.'11       | 1. "PTZ control suddenly might be disabled, then All CH stop recording" fixed. * Rare  | Jan.'11             |