

WV-S8574L(G), WV-S8573L(G), WV-S8564L(G), WV-S8563L(G), WV-S8544L(G), WV-S8543L(G), WV-S8544(G) and WV-S8543(G) Release Note

Version Release Date	Priority Rank Level				Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing	Contents		
	A	B	C	U		Issue (Phenomenon)	Occurrence condition	Correspondence
Ver1.00 April, '22	-					First production		
Ver1.01 (SDK: V1.50) April, '22	B				x	-	-	Supports the camera settings on the [Camera Advanced Setting] window of i-PRO Configuration Tool (iCT) version 3.0.0.1 or later.
				x		The camera incorrectly sends the image of Camera 1 to i-PRO Active Guard, even when AI-VMD alarm is issued by Camera 2, Camera 3 or Camera 4. (Occurrence frequency: High)	When the camera is connected to i-PRO Active Guard.	Fixed.
				x		The camera does not send the Audio detection information to i-PRO Active Guard. (Occurrence frequency: High)	When the camera is connected to i-PRO Active Guard.	Fixed.
		x			The camera restarts. (Occurrence frequency: High)	After setting the area(s) on the [VIQS] window under the following conditions: - [GOP control] is set to "Advanced(Fixed GOP 60s w/1s key-frame)" - [Transmission priority] is set to "VBR"	Fixed.	
Ver1.02 (SDK: V1.50) April, '22	U				x	-	-	Supports the change in parts specification from production in May, 2022*. *Serial number: VExxxxxx Important notice due to this parts change: Firmware version 1.00 and 1.01 are available only for the cameras whose serial number start with VA, VB, VC or VD. Do not downgrade the firmware of VExxxxxx or later production to version 1.00 or 1.01.
Ver2.10 (SDK: V1.60) Aug., '22	B				x	-	-	Changed the color of AI-VMD detection frame at alarm occurrence from blue to red, for the ONVIF connection with Milestone.
					x	-	-	Improved to display the image transmission log on the [Status] tab in the [Maintenance] page. Clicking the "Confirm" button of [Image transmission log] displays logs on a separate window.
					x	-	-	Supports the notification of AI-VMD detection area ID as follows: - Added the [AI-VMD alarm area information] on/off setting to the [TCP alarm notification] window on the [Notification] tab. - Improved the response to the CGI command "/cgi-bin/get_io2" by adding the detection area ID.

*: ONVIF is a trademark of Onvif, Inc.

WV-S8574L(G), WV-S8573L(G), WV-S8564L(G), WV-S8563L(G), WV-S8544L(G), WV-S8543L(G), WV-S8544(G) and WV-S8543(G) Release Note

Version Release Date	Priority Rank Level				Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing	Contents		
	A	B	C	U		Issue (Phenomenon)	Occurrence condition	Correspondence
Ver2.10 (SDK: V1.60) Aug., '22	B				x	-	-	Added the note "Use the latest edition of the software product." to the [Upgrade] tab in the [Maintenance] page and [Software mng.] tab in the [Ext. software] page.
					x	-	-	Improved the human detection performance for extension software. Note: Extension software needs to be updated to the version released in July, 2022 or later.
				x		The 3rd party application on the camera may restart.	-	Fixed.
			x			Unable to perform JPEG image transmission.	When transmitting AI-VMD (WV-XAE200) additional information with the video data.	Fixed.
					x	-	-	Enhanced security.
Ver2.20 (SDK: V1.60) Sept., '22	C				x	-	-	Changed the company name in the GlobalSign digital certificate installed on the camera to "i-PRO Co., Ltd."
				x		The occupancy detection area information is not included in the HTTP alarm notification from the camera.	-	Fixed.
				x		The frame rate and bit rate may not recover once they drop due to the environmental cause.		Fixed.

*: ONVIF is a trademark of Onvif, Inc.