


## Additional waterproof treatment method

### 1. The additional accessories.

- Waterproof ring ..... 1 pc.

### 2. The waterproof treatment method for the Ethernet cable passes.

From the inside, attach the waterproof ring (accessory) to the Ethernet cable by pushing the Ethernet cable through the slit in the waterproof ring, and then block the wiring port with the waterproof ring. Next, perform waterproof treatment with sealant or other methods.



### Additional information

- When a strong light shines on the front of the camera, part of the lens may be reflected on the inside of the dome cover and be visible in images.

#### **IMPORTANT**

- When washing the vehicles, Do NOT use the washing Stock solution of detergent. Always diluted to be used in appropriate concentrations.
- \* When attached to the plastic part, which may be discolored and damaged.

### CORRIGENDA

Important Information contain misdescription. Refer to the following table and confirm the descriptions that are corrected.

#### ■Precautions -[Precautions for use] -Consumable parts

Wrong	Right
Dome cover: PGKV1288ZAC1	Dome cover: PGVF2524ZAC1

#### ■Specifications - Lens - Aperture range

Wrong	Right
E2.2	F2.2