


Operating Instructions

Included Installation Instructions

Wall Mount Bracket

Model No. WV-QWL501

(Heavy salt damage prevention applied)



- Before attempting to connect or install this product, please read these instructions carefully and save this manual for future use.
- The external appearance and other parts shown in this manual may differ from the actual product within the scope that will not interfere with normal use due to improvement of the

i-PRO Co., Ltd. assumes no responsibility for injuries or property damage resulting from failures arising out of improper installation or operation inconsistent with this documentation.

"<Control No.: C****>" used in these documents should be used to search for information on our technical information website (https://i-pro.com/global/en/ surveillance/training-support/support/technical-information) and will guide you to the right information.



Ns0522-0

Printed in China

i-PRO Co., Ltd.

https://www.i-pro.com/

© i-PRO Co., Ltd. 2022

fully.



Caution: Before attempting to connect or operate this product, please read these instructions care-

Notice: This product is not suitable for use in loca-

- tions where children are likely to be present. Do not install this product in locations where
- ordinary persons can easily reach.
- For information about screws and other parts required for installation, refer to the corresponding section of this document.

Precaution

■ Do not use this product except with suitable cameras or brackets.

Failure to observe this may cause a drop resulting in injury.

■ Refer installation work to the dealer.

Installation work requires technique and experiences.

Failure to observe this may cause fire, electric shock, injury, or damage to the product.

■ The measures of protection against snowfall shall be taken.

Weight of snow may cause a fall of the product resulting in injury or accidents. Protect the product against snowfall by installing it under eaves.

■ Do not rub the edges of metal parts with your hand.

Strong rubbing may cause injury.

When using this product, also read the "Precautions" described in the operating instructions for the camera to be attached.

Preface

This product is used for installing the network camera on a wall.



Specifications

Ambient operating temperature:	-50 °C to +60 °C {-	58 °F to +140 °F}	
Dimensions:	120 mm (W) x 220 mm (H) x 269 mm (D)		
	{4-23/32 inches (W) x 8-21/32 inches (H) x 10-19/32 inches (D)}		
Mass:	Approx. 2 kg {4.42 lbs}		
Finish:	Aluminum die cast	Heavy salt damage prevention coating i-PRO white	
Others:	Heavy salt damage	prevention (ISO14993-compliant)	

Precautions for installation

■ In order to prevent injury, the product must be securely mounted to the wall according to the installation guide of this bracket.

■ Installation place

Salt damage prevention is applied to this product. However, it is not completely anti-corrosive. Therefore, consider a place for installation where direct splash of seawater can be avoided. Especially when installing this product in a seashore area or a place where a snow-melting agent is applied, and also where rainwater is avoided, it is recommended to regularly clean and rinse off salt with water. In case of installing this product in a seashore area, regularly check the status of equipment. (Replace the parts as required.)

■ Mounting method for this product

This product is designed to be mounted on a wall. If it is mounted on a desktop or at a slant, the camera may not work correctly and its lifetime may be shortened.

■ Make sure to remove this product if it will no longer be used.

Standard accessories


Operating Instructions (this document)	1 pc.
Cable cap	
Camera mounting screw (Hexagon screw (M6))	5 pcs.
	(of them, 1 for spare)

Other items that are needed (not included)

Fixing screw (M10) or anchor. 4 pcs.

- Minimum pullout strength: 823 N {185 lbf} (per 1 pc.)
- Refer to our technical information website <Control No.: C0120> for information on the minimum pull-out strength.
- Considering the material and strength of the area where the product is to be installed, prepare the screws according to the total weight of the camera and peripheral environment. Use the corrosion-resistant screws, or apply caulking to the screws to be used for fixing the framework and this product.

Parts and functions



Installation/Connections

Be sure to read "Precautions" and "Precautions for installation" before installation.

Refer to the operating instructions of the camera or the bracket for details including the camera or bracket mounting, their adjustment and the cable connection.


The installation of the wall mount bracket is roughly divided into 2 methods. Refer to the applicable description

- When laying cables through the cable access hole (front)
- When laying cables after drilling a hole through the wall

■ When laying cables through the cable access hole (front)


Step 1

Decide the mounting position and then drill holes for fixing screws or anchors in the wall. Procure 4 pieces of M10 fixing screws or anchors to secure the this product on the wall. For screw and anchor, make sure to use the one made of stainless steel, or enough salt damage prevention is applied. The hole diameter for fixing screws or anchors shall be decided in accordance with the fixing screws or anchors to be used. A hole on the wall with a diameter of 30 mm {ø1-3/16 inches) or less for a fixing screw or an anchor can be hidden with this product.




Step 2

Make a slit in the center of the cable cap (accessory) with a cutter.



Step 4


Mount another cable cap (accessory) on the cable access hole (rear) on the plate on the rear side of the bracket.





Step 6

Seal the slit of the cable cap for the prevention of water leakage.




Step 5

Step 3

Mount this product on the wall with fixing screws (4pcs.) (M10: locally procured).


Pass the cable cap through the cable and then

{3-5/32 inches}



Minimum pull-out strength: 823 N {185 lbf}/per 1 pc.

 Apply a waterproofing to the holes for fixing this product on the wall.



Step 7


Refer to each manual of the camera and the bracket for further information about cable connection and how to install the camera or the bracket.

■ When laying cables after drilling a hole through the wall


Step 1

Decide the mounting position, and drill a hole for a fixing screw or an anchor and a hole for cable installation in the wall.

Procure 4 pieces of M10 fixing screws or anchors to secure the this product on the wall. For screw and anchor, make sure to use the one made of stainless steel, or enough salt damage prevention is applied. The hole diameter for fixing screws or anchors shall be decided in accordance with the fixing screws or anchors to be used. A hole on the wall with a diameter of 30 mm {Ø1-3/16 inches} or less for a fixing screw or an anchor can be hidden with this product.



Mount the cable cap (accessory) on the cable access hole (front).




Hole for cable installation: ø38 mm

Step 3

Step 5

through this product.

Make a slit in the center of another cable cap (accessory) with a cutter.



Pass the cables from the wall through the

cable cap (with a slit) on the plate and then

Refer to each manual of the camera and the

bracket for further information about the length


of the cable to be pulled out from the camera

Step 4

Step 6

access hole

After removing the screws (4pcs.) from the rear side of the bracket, remove the plate and mount the cable cap in which a slit was made in Step 3 on the cable access hole (rear).





Mount this product on the wall with fixing

screws (4pcs.) (M10: locally procured).

mounting part. Secure the plate with the screws (4pcs.) removed in Step 4 on the rear side of the bracket. (Recommended tightening torque: 0.78 N·m







823 N {185 lbf}/per 1 pc.

 Apply a waterproofing to the holes for fixing this product on the wall and the cable

Minimum pull-out strength:

Step 7


Refer to each manual of the camera and the bracket for further information about cable connection and how to install the camera or the bracket.

取扱説明書

工事説明付き

カメラ壁取付金具

品番 WV-QWL501



このたびは、弊社製品をお買い上げいただき、まことにありがとうございます。

- 取扱説明書をよくお読みのうえ、正しく安全にお使いください。
- ご使用前に「安全上のご注意」を必ずお読みください。
- この取扱説明書は大切に保存してください。
- 製品の改良などにより、ご使用上影響のない範囲で、記載されている外観などが実際の製 品と異なる場合があります。

取扱説明書に記載されていない方法や、指定の部品を使用しない方法で施工されたことに より事故や損害が生じたときには、当社では責任を負えません。また、その施工が原因で 故障が生じた場合は、製品保証の対象外となります。

i-PRO製品の「お問い合わせ」については、以下の弊社サポートウェブサイト を参照してください。

https://i-pro.com/jp/ja/support_portal

※「日本エリア」でお使いの場合に限ります。日本以外でお使いの場合のサービスは いたしかねます。





i-PRO株式会社

https://www.i-pro.com/

● 取扱説明書をよくお読みのうえ、正しく安全 にお使いください。

注記:

- 本金具は子供がいる可能性のある場所での 使用には適していません。
- 一般の人が容易に触れることができる場所 への設置はしないでください。
- 設置に必要なねじやそのほかの部材などの情報 については本書の該当部分を参照してください。

安全上のご注意 必ずお守りください

人への危害、財産の損害を防止するため、必ずお守りいただくことを説明しています。

■誤った使い方をしたときに生じる危害や損害の程度を区分して、説明しています。

禁止 「死亡や重傷を負うおそ れがある内容」です。



| 注意 「軽傷を負うことや、財産の損害が 発生するおそれがある内容」です。

■お守りいただく内容を次の図記号で説明しています。(次は図記号の例です)



してはいけない内容で



実行しなければならない内容



■ 専用のカメラまたは金具以外は取り付けない (洛下によるけかや事故の原因とはります。)



■ 工事は販売店に依頼する

(工事には技術と経験が必要です。火災、感電、けが、器物損壊の原因とな

⇒ 必ず販売店に依頼してください。 ■ 防雪対策を施す

(雪の重みで落下によるけがや事故の原因となります。) ⇒ ひさしなどで防雪してください。

<u>/</u>() 注意



■ 金属のエッジで手をこすらない (強くこするとけがの原因となります。)

本金具をご使用の際は、取り付けるカメラの取扱説明書に記載された「安全上のご注意」と あわせてお読みください。

商品概要

本金具は、ネットワークカメラを壁面に取り付けるときに使用する取付金具です。



取り付け可能なカメラの最新情報 <管理番号: C0501>

ı	·— ··•·		
	使用温度範囲	-50 ℃~+60 ℃	
	寸法	幅:120 mm/高さ:220 mm/奥行き:269 mm	
	質量	約2 kg	
	仕上げ	アルミダイカスト 耐重塩害塗装 i-PROホワイト	
	その他	耐重塩害仕様 (ISO14993準拠)	

仕様

設置上のお願い

■ 設置工事は電気設備技術基準に従って実施してください。

本金具の設置・接続を始める前に必要な周辺機器やケーブルを確認し、準備してください。接続 する前に、カメラ、PCなど接続する機器の電源を切ってください。

■ 傷害防止のため、本金具は、設置の説明に従って壁面にしっかりと取り付ける必要があります。 ■ 設置場所について

本機器は、耐重塩害仕様として耐食性がありますが、腐食に対して万全ではありません。海水飛 沫が直接当たらない場所に設置するなど、設置場所には十分ご配慮ください。特に海岸地域や融 雪剤を散布される地域で雨水があたらない場所へ設置する場合は、付着した塩分を除去するため に定期的に水で洗い流すなど清掃をお願いします。沿岸部に設置する場合は、機器の状態を定期 的に点検してください。(必要に応じて部品交換などを実施してください。)

■ カメラの取付方法について

本金具は壁取り付け専用です。据え置きや傾けた状態で使用すると、カメラが正常に動作しなかっ たり、寿命が短くなる場合があります。

■ 本金具を使用しなくなった場合は放置せず、必ず撤去してください。

付属品をご確認ください

取扱説明書(本書)	1 #
ケーブルキャップ	2f
取付ねじ (六角穴付きねじ (M6))	5z
	(1本は予備


付属品以外に必要なもの

固定ねじ (M10) またはアンカー

重要

- 最低引抜強度・・・823 N {84 kgf} /1本あたり
- 最低引抜強度の考え方については弊社技術情報ウェブサイト<管理番号: C0120>を参照 してください。
- 金具を固定するねじは、カメラの総質量・周辺環境に合わせて材質・構造を考慮して用意し てください。躯体と本金具間の固定ねじは、耐食処理ねじを使用するか、コーキングを行う など十分に配慮してください。

各部の名前



設置・接続する

取り付ける前に、「安全上のご注意」「設置上のお願い」を必ずお読みください。

カメラや金具の取り付けや、その調整およびケーブルの接続方法などはカメラや金具の取扱説明 書を参照してください。

カメラ壁取付金具の設置方法は以下の2つがあります。

- 該当する設置方法の説明をお読みください。
- ケーブル通し穴(前)からケーブルを通す場合
- 壁に穴をあけてケーブルを通す場合


■ケーブル通し穴(前)からケーブルを通す場合

Step1

取付位置を決め、壁に固定ねじまたはアンカーの穴をあけます。

本金具を壁面に固定する際は固定ねじ(M10)またはアンカーを4本ご用意ください。 固定ねじ、またはアンカーはステンレス製か、または塩害に対して十分に耐食性を有するものを 使用してください。

固定ねじまたはアンカー用の穴径はご使用の固定ねじまたはアンカーに合わせて決めてください。 固定ねじまたはアンカー用の穴径をφ30 mm以下にすると本金具で隠すことができます。





ケーブルにケーブルキャップを通し、本金具の

中へケーブルを通します。その後ケーブル

Step2

ケーブルキャップ(付属品)の中央部にカッター で切り込みを入れます。






(切り込みあり)

Step3


Step4

裏面に付いているプレートのケーブル通し穴 (後)に、もう1つのケーブルキャップ(付属品) 壁面に取り付けます。 を取り付けます。




Step6

ケーブルキャップの切り込み部分を、浸水防止 のためシーリングします。



Step5 固定ねじ4本 (M10: 現地調達) で本金具を



最低引抜強度: 823 N {84 kgf} / 1本あたり}

● 壁面の本金具を固定する穴を防水処理し てください。

Step7


カメラへのケーブル接続やカメラまたは金具の 取付方法については、それぞれの取扱説明書の 設置説明を参照してください。

■壁に穴をあけてケーブルを通す場合

Step1


取付位置を決め、壁に固定ねじまたはアンカーの穴とケーブルを通す穴をあけます。 本金具を壁面に固定する際は固定ねじ (M10) またはアンカーを4本ご用意ください。 固定ねじ、またはアンカーはステンレス製か、または塩害に対して十分に耐食性を有するものを 使用してください。


固定ねじまたはアンカー用の穴径はご使用の固定ねじまたはアンカーに合わせて決めてください。 固定ねじまたはアンカー用の穴径を ϕ 30 mm以下にすると本金具で隠すことができます。



Step2


ケーブル通し穴(前)にケーブルキャップ (付属品)を取り付けます。





Step3

もう1つのケーブルキャップ(付属品)の 中央部にカッターで切り込みを入れます。



壁からのケーブル類をプレートのケーブル


キャップ(切り込みあり)を経由し、本金具

Step4

Step6

を壁面に取り付けます。

本金具の裏面からねじ4本を取り外した後、 プレートを取り外し、Step3で切り込みを入 れたケーブルキャップをケーブル通し穴(後) に取り付けます。




固定ねじ4本(M10:現地調達)で本金具


カメラ取付口からのケーブル引き出し長につ いては、カメラまたは金具それぞれの取扱説 明書を参照してください。 Step4で取り外したねじ4本を使って、 プレートを本金具裏面に固定します。

の中へ通します。

Step5


(推奨締付トルク: 0.78 N·m {8 kgf·cm}) ケーブルキャップの切り込み部分を、浸水防 止のためシーリングします。





Step7

カメラへのケーブル接続やカメラまたは金具 の取付方法については、それぞれの取扱説明 書の設置説明を参照してください。



823 N {84 kgf} / 1本あたり}

最低引抜強度: