

Oct., 2023

The following models are not supported: For these models, please use PSSCT (Panasonic Security System Configuration Tool) V7.x.
 Camera : WV-NF28*, WV-NF302, WV-NP24*, WV-NP304, WV-NP100*, WV-NS202A, WV-NS9* *, WJ-NT304, WJ-NT314, WJ-NW48A, BB-HCM*, BB-HCE*, BL-C*
 Recorder : WJ-HD350, WJ-HD309, WJ-HD316A, WJ-HD180, WJ-HD180

*1: "Camera title position" setting is not supported.

*2: "Language" , "Start Date/time" , "End D

*3: "Upside-down" setting is not supported.

*5: "Max Bit rate" "Smart Coding Mode" setting is not supported

*6: "Adaptive black stretch", "AGC", "DNR" settings are not supported.

*7: For the audio settings, *Unicast Port2(Audi

*8: PC must be able to connect to Internet

*9: "QoS" setting is not supported.

*10: You can launch the "Camera Advanced Settings" function by thumbnail menu. This function supports the W01/G1126, W01/G1536, W01/G1536LTN, W01/G2136, W01/G2236, W01/G2536, W01/G2536LT and W01/G2136.

If the firmware version of the camera is 1.4 or higher, please use version 2.3 or higher of this software.

"Audio input encoding format" and "Audio volume control mode" are not supported.

-WV-S15500, WV-S15700, WV-S22500, WV-S22700, WV-S25500 and WV-S25700, WV

Firmware version 1.01 or higher required.

811: You can launch the "Camera Advanced Settings" function by thumbnail menu. This function supports

If the firmware version of the camera is 1.6 or higher, please use version 2.3 or higher of this software.

*"Audio input encoding format" and "Audio volume control mode" are not supported.

-WV-X1551LN, WV-X1571LN, WV-X2251L, WV-X2271L, WV-X2551LN, WV-X2571LN

*12:Corresponds to the Extension software settings of the following models.(Starts from the thumbnail menu on the main screen.)
W01-G1176, W01-G1576(M), W01-G1156, W01-G1556(M), W01-G71200, E2

813: After "Application update"

*14: Please refer the following.

<https://i-pro.com/global/en/surveillance/training-support/support/technical-information> [C0103]

*15: You can launch the "Camera Advanced Settings" function by thumbnail menu. This function supports the following

- WV-U61300-ZY, WV-U61301-Z1, WV-U65300-ZY, WV-U65301-Z1, WV-U65302-Z2, WV-S65501-Z1, WV-S61501-Z1

*16: You can launch the "Camera Advanced Settings" function by thumbnail menu. This function supports the following models.

*17: You can launch the "Camera Advanced Settings" function by thumbnail menu. This function supports the following models:

- WV-S71300-F3

*18: You can launch the "Camera Advanced Settings" function by thumbnail menu. This function supports the following models.

-WV-U1130A, WV-U1132A, WV-U1142A,WV-U1532LA, WV-U1542LA, WV-U2130LA,WV-U2132LA, WV-U2140LA, WV-U2142LA,

*19: "App. Update" is not supported.

*20: You can launch the "Camera Advanced Settings" function by thumbnail menu. This function supports the following models.
- WV-S4156 WV-S4176 WV-S4556J (M) WV-S4576J (M)

*21: You can launch the "Camera Advanced Settings" function by thumbnail menu. This function supports the following models. "Upside-down" and/or "Image rotation" setting is not supported

- WV-S65340-Z4K, WV-S65340-Z4N, WV-S65340-Z2K, WV-S65340-Z2N, WV-S61302-Z4, WV-S61301-Z2

-WV-S32302-F2L, WV-S35302-F2L, WV-X35302-F2L, WV-S61602-Z3, WV-S61702-Z3, WV-S66300-Z3, WV-S66300-Z3L, WV-S66300-Z4, WV-S66300-Z4L,

WV-S66700-Z3L, WV-X66300-Z3, WV-X66300-Z3L, WV-X66300-Z4, WV-X66300-Z4L, WV-X66600-Z3, WV-X66600-Z3L, WV-X66700-Z3, WV-X66700-Z3L