

WV-XAE203W (AI Non-Mask Detection) Release Note

VER Release Date	Priority Rank Level				Contents		
	A	B	C	U			
Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing							
					Issue (Phenomenon)		
					Occurrence condition		
					Correspondence		
1.00 Dec., '20					First production		
1.10 June, '21	B			x	-	Supports new cameras: WV-S1136, WV-S2136, WV-S2136L, and WV-S2236L *Those cameras need to be upgraded to version 1.11 or later to use WV-XAE203W.	
				x	-	Supports detection frame display on i-PRO Configuration Tool version 2.0*. *To be released in the end of June.	
				x	The image may not be displayed at the frame rate selected in [Frame rate*]. (Occurrence frequency: High)	In case of simultaneous operation of AI Privacy Guard (WV-XAE201) and WV-XAE203W	Added the function to limit the frame rate of the target stream for WV-XAE201W to fix this phenomenon: - Up to 10 fps for WV-X series camera - Up to 5 fps for WV-S series camera
				x	The demo screen does not appear. (Occurrence frequency: High)	When the number assigned to [HTTP port] is not "80" in the camera setting	Fixed.
			x		WV-XAE203W restarts. (Occurrence frequency: High)	When the demo screen is opened and closed repeatedly.	Fixed.
				x	-	-	Improved the visibility of the demo screen as below: - Changed the color of "Unknown status" frame from green to blue - Removed the status display for blue frames ("Unknown" and "Mask")
1.10 June, '21	B			x	Alarm occurrence indication button on the live image and the detection frames on the demo screen may not be displayed. (Occurrence frequency: Rare)	Fixed.	
				x	-	-	Supports new cameras: WV-S8543, WV-S8543G, WV-S8544, WV-S8544G, WV-S8543L, WV-S8543LG, WV-S8544L, WV-S8544LG, WV-S8563L, WV-S8563LG, WV-S8564L, WV-S8564LG, WV-S8573L, WV-S8573LG, WV-S8574L, WV-S8574LG
1.20 Mar., '21	U			x	-	-	Supports new cameras: WV-S8543, WV-S8543G, WV-S8544, WV-S8544G, WV-S8543L, WV-S8543LG, WV-S8544L, WV-S8544LG, WV-S8563L, WV-S8563LG, WV-S8564L, WV-S8564LG, WV-S8573L, WV-S8573LG, WV-S8574L, WV-S8574LG
1.30 May, '22	C			x	This extension software may not start after the camera is restarted. (Occurrence frequency: Rare)	When the following 1 and 2 are performed on the applicable camera. Applicable camera: WV-X1551LN, WV-X2551LN, WV-X2251L, WV-X1571LN, WV-X2571LN, and WV-X2271L 1. Register the Registration key of this extension software on version 1.30 of the above camera 2. Then, upgrade firmware of the camera from version 1.30 to 1.40 or later	Fixed.

WV-XAE203W (AI Non-Mask Detection) Release Note

VER Release Date	Priority Rank Level				Contents		
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence
1.30 May, '22	C				-	-	Supports the "Light" mode (white background) of the camera screen setting. Note: Camera firmware with "Light" mode implemented will be released in July, 2022.
1.40 Sept., '22	U				-	-	Supports new cameras*. *Details including model numbers will be announced in "Compatibility list for extension software" (Control number: C0103) at the following URL in December, 2022 or later. https://i-pro.com/global/en/surveillance/training-support/support/technical-information