

| VER Release Date | Priority Rank Level | | | | Issue (Phenomenon) | Occurrence condition | Correspondence | |
|---------------------|---------------------|---|---|---|--|--|---|---|
| | A | B | C | U | | | | |
| 1.00 Dec., '20 | | | | | First production | | | |
| 1.10 June, '21 | B | | | | - | - | Supports new cameras: WV-S1136, WV-S2136, WV-S2136L, and WV-S2236L *Those cameras need to be upgraded to version 1.11 or later to use WV-XAE203W. | |
| | | | | | - | - | Supports detection frame display on i-PRO Configuration Tool version 2.0*. *To be released in the end of June. | |
| | | | | x | | The image may not be displayed at the frame rate selected in [Frame rate*]. (Occurrence frequency: High) | In case of simultaneous operation of AI Privacy Guard (WV-XAE201) and WV-XAE203W | Added the function to limit the frame rate of the target stream for WV-XAE201W to fix this phenomenon: - Up to 10 fps for WV-X series camera - Up to 5 fps for WV-S series camera |
| | | | | | x | The demo screen does not appear. (Occurrence frequency: High) | When the number assigned to [HTTP port] is not "80" in the camera setting | Fixed. |
| | | | x | | | WV-XAE203W restarts. (Occurrence frequency: High) | When the demo screen is opened and closed repeatedly. | Fixed. |
| | | | | | x | - | - | Improved the visibility of the demo screen as below: - Changed the color of "Unknown status" frame from green to blue - Removed the status display for blue frames ("Unknown" and "Mask") |
| 1.10 June, '21 | B | | | | Alarm occurrence indication button on the live image and the detection frames on the demo screen may not be displayed. (Occurrence frequency: Rare) | - | Fixed. | |
| | | | | | - | - | Improved the visibility of the demo screen as below: - Changed the color of "Unknown status" frame from green to blue - Removed the status display for blue frames ("Unknown" and "Mask") | |
| 1.20 Mar., '21 | U | | | | - | - | Supports new cameras: WV-S8543, WV-S8543G, WV-S8544, WV-S8544G, WV-S8543L, WV-S8543LG, WV-S8544L, WV-S8544LG, WV-S8563L, WV-S8563LG, WV-S8564L, WV-S8564LG, WV-S8573L, WV-S8573LG, WV-S8574L, WV-S8574LG | |
| 1.30 May, '22 | C | | | x | This extension software may not start after the camera is restarted. (Occurrence frequency: Rare) | When the following 1 and 2 are performed on the applicable camera. Applicable camera: WV-X1551LN, WV-X2551LN, WV-X2251L, WV-X1571LN, WV-X2571LN, and WV-X2271L 1. Register the Registration key of this extension software on version 1.30 of the above camera 2. Then, upgrade firmware of the camera from version 1.30 to 1.40 or later | Fixed. | |



WV-XAE203W (AI Non-Mask Detection) Release Note

This document describes software package upgrade for WV-XAE203W.
 1. Release version: 1.20
 2. Release Note Reference Number: WV-XAE203W_004

May 31, 2022
 i-PRO Co., Ltd.

| VER Release Date | Priority Rank Level | | | | Contents | | |
|---------------------|---------------------|---|---|---|--------------------|----------------------|---|
| | A | B | C | U | Issue (Phenomenon) | Occurrence condition | Correspondence |
| 1.30 May, '22 | C | | | | - | - | Supports the "Light" mode (white background) of the camera screen setting. Note: Camera firmware with "Light" mode implemented will be released in July, 2022. |