



CORRIGENDA

Installation procedure leaflet contain misdescription. Refer to the following table and confirm the descriptions that are corrected.

Incorrect	Correct
<p data-bbox="145 370 285 426">Step7</p>  <p data-bbox="560 751 767 813">! <u>0.78 N·m</u> <u>{0.58 lbf·ft}</u></p>	<p data-bbox="823 370 963 426">Step7</p>  <p data-bbox="1241 751 1449 813">! <u>1.2 N·m</u> <u>{0.89 lbf·ft}</u></p>



* PGQW2444ZA *



avs0322-0
Printed in China

正誤表

設置手順チラシに記載の誤りがありました。以下に内容を記載します。

誤	正
<p data-bbox="145 337 288 393">Step7</p>  <p data-bbox="544 712 775 768">! <u>0.78 N·m</u> {8.0 kgf·cm}</p>	<p data-bbox="823 337 967 393">Step7</p>  <p data-bbox="1222 712 1469 768">! <u>1.2 N·m</u> {12.2 kgf·cm}</p>